

QUICK GUIDE

THUNDERBOLT 4 DOCK


1 Connect the power adapter from the dock's DC input port directly to a wall outlet.




2 Using the included cable, connect the dock to your host device from its Thunderbolt 4 host port.




3 Connect up to three USB-C devices to the dock's Thunderbolt 4 ports.
Supports 40 Gbps data transfer & 15W charging each port. Supports dual 4K HDMI output up to 60Hz total.




4 Connect a RJ45 cable to the dock's Gigabit Ethernet port.



5 Use the three USB-A 3.2 data ports for fast transfer & back up – up to 10 Gbps.



6 Use the USB-A charging port to power an USB device – up to 7.5W.



7 Insert an SD card into the dock's UHS-II card reader slot.

